

9/97/CtAw/200

**SAFETY REGULATION GROUP**  
Aircraft Maintenance Standards Dept



Tapestry Colour Ltd  
51 Frith Street  
LONDON  
W1V 5TE

Aviation House  
Gatwick Airport South  
West Sussex RH6 0YR

Switchboard: (0293) 567171  
Fax: (0293) 573999  
Telex: 878753

16 December 1992

Dear Sir

**STAMPE SV4 SERIES AIRCRAFT  
INSPECTION OF LIFTWIRE ATTACHMENT FITTINGS**

Further to our letters to Owners/Operators Nos.1217 and 1217 Issue 2, the CAA has decided to publish an Airworthiness Directive on the above subject.

CAA Airworthiness Directive 002-12-92 will be published in the December amendment to CAP 474 - Foreign Airworthiness Directives as the following:-

Applicable to Stampe SV4 Series aircraft. Compliance is required at the next tie rod replacement in accordance with CAA AD 011-03-88, not later than 100 or 500 flight hours as appropriate.  
Inspect by visual and NDT methods the lift wire attachment brackets for general condition and cracks in accordance with paragraphs 1 to 5 of DGAC Airworthiness Directive 75-90.  
Repeat inspection at 500 flight hour intervals.

Note: An English translation of DGAC AD 75-90 is attached for ease of reference.

This Airworthiness Directive cancels LTO 1217 and 1217 Issue 2.

Yours faithfully

A handwritten signature in black ink, appearing to read 'H J Neal', written in a cursive style.

H J NEAL  
Aircraft Maintenance Approvals  
Tel 0293 573239